# **CORN COB MEDIA MSDS**

#### SECTION I

PRODUCT NAME OF NUMBER	
Corn Cob Media	
MANUFACTURED FOR	EMERGENCY TELEPHONE NO.
The Easthill Group dba/ The Eastwood Company	Chem-Trec 800-424-9300
ADDRESS(NUMBER,STREET,CITY,STATE AND ZIP CODE)	
263 Shoemaker Road USA & Canada: 800-345-1178	
Pottstown, PA 19464 Outside USA: 610-323-2200	
MATERIAL DESCRIPTION, PROPER SHIPPING NAME	
Corn Cob Scrap	
HAZARD CLASSES	
Non-regulated	
CHEMICAL FAMILY	FORMULA
N.A.	N.A.

# SECTION II– INGREDIENTS

CHEMICAL NAME(S)	APPROX.%	Listed as a Carainagon In NTD IAPC
CHEIMICAL NAME(S)	AFFRUA.%	Listed as a Carcinogen In NTP, IARC
		OR OSHA 1901(Z) (specify)
Calcium	0.1	NO
Phosphorus	0.08	NO
Crude Protein	2.0	NO
Coarse Fibred	28.2	NO
Coarse Ash	2.0	NO

# SECTION III- PHYSICAL DATE

SOFTENING POINT °F °C	N.A.	
VAPOR DENSITY(AIR =1)	N.A.	
SOLUBILITY IN WATER	Nil	
MATERIAL FORM: Solid		
APPEARANCE AND ODOR scrap, Beige color, No specific Odor		

# SECTION IV- FIRE AND EXPLOSION HAZARD DATA

FLASH POINT °F °C N.A.	LEL N.A.	UEL N.A.
FLAMMABLE LIMITS : Flammable		

# SECTION V- HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE-Conditions To Avoid THRESHOLD LIMIT VALUE PERMISSIBLE EXPOSURE LIM	Т
--	---

#### EW #13450 - Dry Shine III Tumbler Media-15 lbs

Mechanical injury to eyes and/or skin can occur. Excessive dust inhalation may be harmful. N.A.

PRIMARY ROUTES OF ENTRY X inhalation x skin contact x other (specify) eye through mechanical contact only.

EMERGENCY AND FIRST AID PROCEDURES in case of irritation flush eyes or skin with water. In case of excessive inhalation of dust

Remove to fresh air. Call physician if necessary

# SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID	N.A.
	STABLE	Х		
INCOMPATIBILITY (materials to avoid) No specific incompatibility				
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID	N.A.
	MAY NOT OCCUR	Х		

# SECTION VII - SPILL OR LEAK PROCEDURES

 STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Sweep or vacuum up and place waster in disposal container.

 WASTE DISPOSAL METHOD Disposal must be made according to Federal, State and Local regulations.

 CERCLA (Superfund) REPORTABLE QUANTITY (in lbs)
 N.A.

 RCRA HAZARDOUS WASTE NO. (40.CFR 261.33)
 N.A.

 Volatile organic compound (voc) (AS PACKAGED, MINUS WATER )
 N.A.

 Theoretical lb/gal
 Analytical lb/gal

# SECTION VIII- SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (specify type)Provide adequate ventilation. NIOS / MSHA approved respiratory protection as required.			
VENTILATION	LOCAL EXHAUST (Specify Rate) As required for specific user application.		SPECIAL
	MECHANICAL (Greneral-Specify Rate) See Section IV and IX "Other Precautions		OTHER
PROTECTIVE GLOVES (Specify Type) Normal Work Gloves EYE PROTECTION (Specify Type			Type) Safety Goggles
OTHER PROTECTIVE EQUIPMENT N.A.			

# SECTION IX- SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep dry to maintain material in usable condition. Store in original containers to maintain identity.

OTHER PRECAUTIONS Determine compliance with OSHA 1910.1000 Table Z-3 "inert or Nuisance Dust"